

ARRANGEMENT OF THE DOCK AREA

This unit is designed for grade level location. If local conditions warrant, the Restraint Console may be located above grade. The Manufacturer recommends limiting above grade mounting to less than 2" to maintain clearance for projected new standards allowing lower ICC frame sections.

The success and strength of any installed product relies heavily on the conditions of the material surrounding the installation site. This will include the dock face and adjoining drive area for the MVR-100 (MVR-103 & MVR-105) Vehicle Restraint. Repair any structural defects to the dock face and/or drive prior to attempting equipment installation. If necessary, prepare alternate attachment methods to accommodate on-site conditions or contact the manufacturer to assist in preparation of accessories needed to adequately secure this project.

